

General Environmental Incident Summary

Incident: 4147 **Date/Time Notice:** 6/27/2016 1000 **DEM Incident No:**
Responsible Party: BEKK's Hot Oil Service, Inc
Date Incident: 6/26/2016 **Time Incident:** 1040 **Duration:** 2 hours
County: McKenzie **Twp:** 150 **Rng:** 101 **Sec:** 18 **Qtr:**
Lat: 47.80864 **Long:** -103.65520 **Method:** Interpolation from map
Location Description: 2 miles south of alexander, 1/4 mile west on county road 15

Submitted By: Lori Erickson **Affiliation:** secretary
Address: PO Box 197
City: Williston **State:** ND **Zip:** 58802

Received By:

Contact Person: Mike Erickson
P.O. Box 197
Williston, ND 58802

Distance Nearest Occupied Building: 50 Feet **Release Contained:** Yes

Type of Incident: Vehicle Accident

Description of Released Contaminant: Freshwater & hydraulic oil

Volume Spilled: 10.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

Truck tipped over & broke hydraulic hose & approximately 10 gallons of hydraulic oil leaked onto roadway

Risk Evaluation:

none

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

none

Action Taken or Planned:

Put down oil absorbant on ground that had spill on it

Wastes Disposal Location:

Agencies Involved: Local Fire Department, Local Law Enforcement, Local Emergency Manager

Updates

Date: 6/27/2016 ***Status:*** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Volume:

Notes:

Further follow-up needed.

Date: 7/11/2016 ***Status:*** Inspection

Author: Schiermeister, Robin

Updated Volume:

Notes:

Arrived on site on 7-7-16 around 5:00. The fluid was cleaned up and the contaminated soil removed. Further follow-up is needed to check for vegetation.